

2006 BOMBARDIER CHALLENGER 604



Specifications/Descriptions are provided as information and do not constitute representations or warranties of ACASS Canada Ltd. You should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to ACASS Canada Ltd., its clients, and their counsel.

ACS-1218



HIGHLIGHTS

AIRFRAME ENROLLED ON SMART PARTS

ENGINES ENROLLED ON JSSI

APU ENROLLED ON MSP GOLD

36 MONTH INSPECTION C/W APRIL 2024

NEW PAINT 2021

INTERIOR REFURBISHMENT 2021

AIRFRAME

TOTAL TIME 5,366 LANDINGS 2,180

PROGRAM Smart Parts

ENTRY INTO SERVICE DATE 2006

ENGINES

MAKE/MODEL GE CF-34-3B

TSN LEFT: 5,366 RIGHT: 5,366 CSN LEFT: 2,180 RIGHT: 2,180

PROGRAM JSSI

APU

MAKE/MODEL GTCP 36-150 (CL)

TSN 7,114 **PROGRAM** MSP



AVIONICS

FDR:

ADF: Dual Collins ADF-462

DME: Dual Collins DME-442

EFIS: Collins 6-tube

Flight Director: Collins FCC-4006

FMS: Dual Collins FMS-6000 w/dual GPS-4000

L3 FA-2100

Hi Frequency: Dual Collins HF-9031A

Communication Radios: Dual Collins VHF-422C

Navigation Radios: Dual Collins VIR-432

Radar Altimeter: Dual

TAWS: Honeywell Mark V EGPWS
TCAS: Collins TTR-921 w/change 7

Transponder: Dual Collins TDR-94D Mode S

Weather Radar: Collins RTA-854 w/dual controllers & lightning detection

ELT: C406-2
GPS: GPS 4000S
SATCOM: ICS 200

INTERIOR

NUMBER OF PASSENGER SEATS Twelve

GALLEY LOCATION Forward

GALLEY EQUIPMENT Microwave oven, coffee machine

FORWARD CABIN CONFIGURATION Four-place club seating

AFT CABIN CONFIGURATION Four-place conference group opposite

a three-place berthable divan, (cushioned for 3, belted for 4)

LAVATORY LOCATION Aft

JUMPSEAT INTERIOR REFURBISHMENT Yes

INTERIOR REFURBISHMENT 2021

EXTERIOR

BASE COLOR White

STRIPES Blue & Gray

NEW PAINT 2021

















































ĀCASS OWN YOUR JOURNEY®





